

FORMSTRIP 101

Degreaser and decarboniser for ferrous metals.

Applications:

Formstrip 101 is recommended where light build-up of rust exists. It also removes grease and carbon deposits. It is used in the precleaning of engines for motor vehicles, trucks, and locomotives prior to reconditioning.

Formstrip 101 can be safely used on mild steel, stainless steel and copper components. Formstrip 101 must NOT be used on aluminium, brass, bronze, solder or other white metals as aggressive chemical attack on these metals will occur.

Use Directions

Formstrip 101 is used in immersion tanks. Best results are obtained when solutions are hot and agitated. As the operating conditions of Formstrip 101 baths are related to the quantity and composition of soil encountered, the following general conditions are listed as a guide.

Concentration: 75 to 150 grams per litre
Temperature: 85 to 100°C
Immersion Time: 15 minutes to 2 hours

Hazards

When the product is added to water, very large quantities of heat are liberated. To minimize this vigorous reaction it is recommended that the product is added to cold water and is spread out evenly along the length of the tank with agitation. Under NO circumstances should the entire product be added in a corner as vigorous reaction can occur which can cause an eruption of very corrosive liquid in the tank.

For those who prefer a liquid product Formstrip 404 is recommended.

Caution

Formstrip 101 contains caustic soda. It is recommended that operators wear safety glasses and gloves when handling the product or solutions of the product.

Environmental Considerations

Formstrip 101 should never be discharged directly into the environment. Formstrip 101 should always be neutralized with Chemform's MA-33 when it reaches the end of its operational life.

Your Chemical Formulators Representative will perform the neutralization on request.

First Aid

If poisoning occurs, contact a doctor or Poisons Information Centre. If swallowed, do NOT induce vomiting, give a glass of water. If skin contact occurs, remove contaminated clothing and wash skin thoroughly. If in eyes, hold eyes open, flood with water for at least 15 minutes and see a doctor.

Packages

25 kilo bags

PI03/02